

Download 2000 F250 V10 Triton Manual

From what I have been told the knock sensor on a Ford Triton V10 is under the intake manifold. According to local Ford Dealer intake manifold has to be removed to replace the sensor. I have a Ford F250 V10 Triton that snapped the right side valve cam. Had to replace head and cam shaft new gaskets are - Answered by a verified Ford Mechanic. For the 2005 model year, the Ford Super Duty trucks were given exterior and interior updates. For the exterior, a new grille, front bumper, and headlights were introduced alongside the introduction of a locking tailgate for all pickup trucks. Under the skin (with thicker frame rails), updated Triton gasoline engines were introduced with higher engine output and larger alternators; in response ... Does anyone know the likeability and mpg of the 6.8L V10 - I have a 2008 6.4L Diesel and I'm having problems with the mileage being much less than my 2005 ...